

Product Advisory

Issue Date: February 5, 2020

Change Type:

Label related: Advisory regarding the RoHS status on the labels

Parts Affected:

See list of affected part numbers in the Appendix.


Effect of Change on Fit, Form, Function, Quality, or Reliability:

There is no change to Fit, Form, Function, Quality, or Reliability due to this product advisory.

Description and Extent of Change:

Due to a change in the EU RoHS Directive deadline for Exemption 15, the RoHS status on the label will not accurately reflect the correct compliance information after February 29, 2020. The customer must convert to the RoHS compliant part number.

The typical location of the RoHS designation is indicated below.



RoHS designation status:

- March 1, 2020 and later: The label information is not valid.

Reasons for Change:

For these products, Exemption 15 to RoHS compliance per the EU RoHS directive expires on February 29, 2020.

Effective Date of Change:

March 1, 2020



Appendix:

The affected part numbers are included in the table below.

BCM54942AKFSBG	BCM84728MAIFSBG	BCM84756CKFSBG	BCM84833B1KFEBG
BCM84064A1KFSBG	BCM84729AIFSBG	BCM84756LCKFSBG	BCM84848A1KFSBG
BCM84074AIFSBG	BCM84729MAIFSBG	BCM84757C1KFSBG	BCM84846A1KFSBG
BCM84168AKFSBG	BCM84740A1KFSBG	BCM84757CKFSBG	BCM84833B1KFSBG
BCM84318AKFSBG	BCM84741CKFSBG	BCM84758AKFSBG	BCM84834B1KFEBG
BCM84328BKFSBG	BCM84742AKFSBG	BCM84759CIFSBG	BCM84834B1KFSBG
BCM84520A1IFSBG	BCM84747AIFSBG	BCM84764AKFSBG	BCM84836B1KFEBG
BCM84540A1IFSBG	BCM84747AKFSBG	BCM84780AKFSBG	BCM84844A1KFSBG
BCM84722AIFSBG	BCM84748AIFSBG	BCM84784AKFSBG	BCM84333B1KFSBG
BCM84722MAIFSBG	BCM84748AKFSBG	BCM84790A1IFSBG	BCM84334B1KFEBG
BCM84727AIFSBG	BCM84752A1IFSBG	BCM84790A1KFSBG	BCM84847A1KFSBG
BCM84728AIFSBG	BCM84753A1KFSBG	BCM84793A1KFSBG	BCM84823B1KFSBG
BCM84728AKFSBG	BCM84754A1KFSBG	BCM84794A1KFSBG	BCM84823LB1KFSBG

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.